



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director  
JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
**July 16, 2009**

Reviewed: L/K

<b>Mine Name:</b> Travertine #1	<b>Permit Number:</b> M/023/0042
<b>Operator Name:</b> BEG Resources	<b>Inspection Date:</b> July 14, 2009
<b>Inspector(s):</b> Wayne Western	<b>Time:</b> 2:10 pm – 2:30 pm
<b>Other Participants:</b> None	<b>Mine Status:</b> Reclaimed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

This was a routine inspection.

**Inspection Summary:**

The Division on May 4, 2009 evaluated the site for vegetation. The Division found during the May 4, 2009 inspection that the vegetation met the 70% pre-mining cover standard. During the July 14, 2009 inspection, the Division found that the site was stable and that the road to and around the site was adequately maintained.

**Conclusions and Recommendations:**

The Division needs to request BLM concurrence to close this file. Once received, the Division can release the surety and close this file.

**Directions:**

1.6 miles north of Soma Quarry. Road to site is 0.1 miles south of mile marker 14. Site is approximately 0.6 miles from pavement. Go west on the road, which then turns east then south.

Inspector's Signature

*Wayne W. Winters*

08/10/2009

WHW:vs

cc: Gary Burningham, Operator

Jerry Mansfield, BLM-Filmore

O:\M023-Juab\M0230042-Begtravertine\inspections\ins\_07142009.doc



Panorama of site



Panorama of site



Panorama of site



Panorama of site